



Slope Stabilization of a Section of the Welland Canal



Dennis E. Becker
Ph.D, P.Eng., FEIC, FCAE

Principal
Golder Associates

**GRC Distinguished
Alumni Speaker**

April 2012

Outline of Presentation


- History and Background
- Site Description and Subsurface Conditions
- Ground and Structure Movement Summaries
- Remedial Measures
- Analysis and Design Criteria
- Performance
- Construction








Map



Site Location



History and Background


- Constructed from 1913 to 1933
- Marginal stability and slope failures
- Movement and repairs to main pier foundations
- West bank and west main pier of Bridge 4 focus of presentation



Canal Excavation History

- Started in 1913 with 2H:1V cut slopes
- East bank failed in 1917
- Flatten slopes to 3H:1V
- West bank failed in 1921 near Bridge 4
 - Buried 85 ton shovel
- More failures between 1922 and 1924
- Widening (berm profile) in 1925 and 1926
- Several slides between 1928 and 1933 in vicinity of Bridge 4





Welland Ship Canal
Hospital

Fig. 13 c.

Canal Limits

300

BRIDGE N° 4

290

280

270

Canal
Lands

Drainage Ditch

PONDAGE FOR LOCK N° 2
Area 200.0 Acres
Water Level, 335.5

HOMER

Canal Limits

337.5


330

10 Mile Creek

Canal Limits

From
Queenston

(1058.F.)



Canal Excavation History (cont)

- Canal deepened 0.6 m in 1957
- More slope failures – stabilized by rockfill toe berms
- In 1989 upper banks cut back and Bridge 4 lengthened
- In 1996 significant slope movement observed in SI during dewatering
- In 1999 slope failure immediately north of Bridge 4






Bridge 4 History



- Important transportation link
- Clear span of 60 m with total length of 190 m
- Timber pile foundation
 - 1913 to 1926 construction
 - failure in 1917 (east pier moved 3 m)
 - east pier foundation reconstructed by 1920
 - 1926 additional piles driven to support new double-leaf bascule bridge
 - caused west main pier to move
 - jacked piles to refusal







Bridge 4 History (cont)


- Bridge structure construction 1927 to 1928
- In 2000 bascule jaws binding and substantial wear
- Estimated movement (closure) of 30 mm
- Bridge superstructure in satisfactory condition





East

West



Bridge 4

West

East



FIG. 925. BRIDGE NO. 4; CLOSED.



Bridge 4: circa 1930 - 1940



West

East



Bridge 4: 2001



Main East Pier - Bridge 4: 2003


Canal Operation

Season from April to December

Drained every few years in off-season or as required for maintenance



Geotechnical Investigation



Field:


- 20 sampled boreholes & field vanes
- 25 CPTs
- 5 PMTs
- 5 slope indicators

Laboratory:


- index and classification
- oedometer
- triaxial
- direct shear

Site Stratigraphy

- 6 m sand and gravel (upper banks)
- 20 m soft to stiff silty clay
- 2 m very stiff clayey silt
- 5 m very dense sandy silt till
- shale bedrock – Queenston Formation
 - upper 1 m weathered



Silty Clay Deposit



- undrained shear strength: 20 to 60 kPa
- water content: 20 to 42 %
- liquid limits: 33 to 47
- plasticity index: 15 to 25
- OCR: 1.3 to 1.9
 - weakened zones: 15 kPa close to bridge
- S_u/σ_p^1 : 0.19 - 0.30
- effective friction angle: 22 to 26°
- effective cohesion: 20 to 0 kPa
- Cone Factor (N_k) = 19

Silty Clay Weak Zones

- Within silty clay exist pre-shear (weakened) zones as a result of past slope failures / ground movement
- Confined to within lower bank above base of canal
- No deep weakened zones




Stability Analysis

- Slope/W – Morgenstern-Price
- Back Analysis:
 - original construction
 - 1999 failure (lower bank)
 - localized lower bank (weakened zones)
- Canal bank only marginally stable at low canal level
- Design Analysis:
 - lower bank (with wall) stability
 - overall bank stability



Summary of Stability Analyses





| | CASE | <u>FS</u> |
|----------------------|-------------|---|
| Original | 2H:1V | ≤ 1.0 |
| | 3H:1V | 1.38 canal filled 1.15 canal empty |
| January 1999 Failure | | >2 (average undisturbed strength $S_u = 45$ kPa) >1.6 (lower bound $S_u = 35$ kPa) 1.0 ($S_u = 15$ to 20 kPa - close to remoulded) |

Slope Indicator Readings

- Monitored ground and pier structure movements since 1986
- Slope moved laterally by as much as 230 mm as a result of cycles in operational canal water levels
- Pier movement essentially elastic
 - Permanent plastic deformation of 3 mm to 6 mm in 15 years
- Pier movement due to ground movement adjacent to pier











5. FOR LOCATION OF SECTION REFER TO FIGURE 2.



OFF-SET FROM CANAL CENTRELINE


SECTION A-A

Date: 11/11/03




SECTION C-C

West Bank Movements




History of Slope Indicators 52 and 53
6 m depth




Profile of Slope Indicator 52
Pre and Post 1999 Slope Failure

West Pier Movements



History of Slope Indicator 64
6 m depth




Response of Slope Indicator 64
after 1999 Bank Failure

Possible Remedial Measures




- Minimize number of canal dewatering cycles
- Soil Reinforcement:
 - micro-piles on both sides adjacent to west main pier
 - 600 piles 20 m long
 - \$ 2.5 M
- Structural Wall:
 - anchored caisson wall on both sides adjacent to west main pier
 - 100 m total length: 30 m deep
 - \$2.7 M

Conceptual Plan – Scheme 1 Pile Reinforced Soil and Slope Regrading Reach 2 Feasibility Study, Welland Canal



Conceptual Plan – Caisson Wall – Scheme 3 Reach 2 Feasibility Study, Welland Canal



Plan of Anchored Caisson Wall

South

North





Figure 8 – Plan view of Caisson Wall System.



Caisson Wall

- 54 m on north side and 69 m on south side of Bridge 4
- 1.07 m diameter – 159 piles in total
- H-piles at 1.5 m spacing to top of weathered bedrock – 80 piles in total
- Filler piles to 15 m depth (≥ 3 m below observed weakened zones) – 79 piles in total



Caisson Wall (cont)

- Designed to be “stiff”:
 - maximum deflection of 15 mm at top of wall and 3 mm at base of canal
- Anchorage Caissons at 3 m spacing
 - total of 41 caissons, 1.22 m diameter
 - placed to top of fresh bedrock




Earth Pressures on Wall

- Conventional analysis
- Wall friction considered
- Both short- and long-term conditions analysed
- Canal in dewatered state basis of design
- Undrained condition governed design
 - lower net lateral pressure
 - representative of repeated canal dewatering cycles



Earth Pressures on Wall (cont)

Lateral Net-Pressure Diagram




Anchors

- Anchored into shale bedrock
- Approximately 40 m free length (FREEEL)
- 6 m bond length in shale bedrock (BONDL)
- Allowable bond stress:
 - 350 kPa in shale bedrock
- Anchor load of:
 - 600 kN – proof tests
 - 900 kN for performance tests




Anchors (cont)

- All anchors satisfied performance specification:
 - elongation: > 60% of elastic elongation of FREEL
< 100% of elastic elongation of (FREEL + 0.5x BOND L)
 - creep not exceed 2 mm during final time log cycle



Anchors (cont)



Tieback Pile and Caisson Wall Performance




- Lateral movement monitored during anchor testing
- At 900 kN (150% design load):
 - tieback pile moved 17 mm to 27 mm (westward)
 - Tieback pile movement to 8 m depth
 - top of caisson wall moved 4 mm (westward)
 - movement to 8 m depth

Tieback Pile and Caisson Wall Performance (cont)


- At 600 kN (design load) after 5 days
 - tieback pile rebounded 2 mm
 - top of caisson wall moved additional 2 mm westward (6 mm)
- After 9 months caisson wall net westward movement (± 3 mm)




History of SI-52 and SI-53 at 6 m Depth




History of SI-64 at 6 m Depth (East-West Direction)



History of SI-64 at 6 m Depth (North - South Direction)



SI-64 Profile for Complete Canal Dewatering Cycles



Construction Highlights

- Constructed between November 2001 and February 2002
 - Total cost of CAN \$2.4 Million
 - Canal dewatered December 2001 for maintenance
 - Wall portion completed prior to dewatering to minimize risk of bank / pier movement


Anchorage Caissons south of Bridge



- Construction carried out along west bank
 - No disruption to Canal operations
 - Equipment not placed on lower slope where shear strengths as low as 15 kPa exist
 - Toe berms along lower slope maintained
- Lower slope in front of wall regraded after wall in place to improve stability


















































Project Participants

- **SLSMC (Seaway): Owner**
 - Mike Whittington, P.Eng.
 - Rudy Lee, P.Eng.

- **Golder Associates: Prime Consultant**
 - Dennis Becker, P.Eng.
 - Dan Breeze, P.Eng.
 - Andrew Walker, P.Eng.

- **Isherwood Associates: Caisson Wall Design**
 - Nadir Ansari, P.Eng.



Project Participants (cont)

- Delcan Corporation: Bridge Structure
 - Tim Wright, P.Eng.
- Deep Foundations Contractors Inc.: Contractor
 - Bill Starke, P.Eng.
 - Ross Maltman, P.Eng.
 - Ken Dawson
 - Edward Kolakowski





THANK YOU